
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/2/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S07MM1022MH	Test ID: <u>D1032-034034</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S07MM1022MH
0			Water Level	
13.69999981	10		Tap Factory	FROM 3633
13.69999981			Dye Test Visible	@ TF - downspout
72.90000153	10		Tap Factory	FROM 3625
72.90000153			Dye Test Visible	@ TF - downspout